

End Of Life Announcement

Diva Server BRI-2M PCI

Eicon Networks has decided to withdraw the following products from the marketplace:

- Diva Server BRI-2M PCI
- Diva Server BRI-2M PCI Australia
- Diva Server BRI-2M PCI Japan
- Diva Server BRI-2M PCI Germanic
- Diva Server BRI-2M PCI + NT1
- Diva Server BRI-2M PCI UK

Migration Path

The table below shows the replacements and the respective ordering numbers for discontinued products.

EOL product	Product code	Suggested Replacement	Product code
Diva Server BRI-2M PCI	305-206	Diva Server BRI-2M 2.0	306-162
Diva Server BRI-2M PCI Australia	306-177	Diva Server BRI-2M 2.0 Australia	306-192
Diva Server BRI-2M PCI Japan	305-261	Diva Server BRI-2M 2.0	306-162
Diva Server BRI-2M PCI Germanic	305-291	Diva Server BRI-2M 2.0	306-162
Diva Server BRI-2M PCI + NT1	305-441	Diva Server BRI-2M 2.0 + NT1	306-165
Diva Server BRI-2M PCI UK	305-946	Diva Server BRI-2M 2.0 UK	306-164

Support and Inventory Policy

These products are no longer manufactured and sold by Eicon. EOL products will not receive software feature updates or support for new operating systems.

Telephone and email installation advice for EOL products is provided where drivers are available for currently supported operating systems.

All contractual warranties for the above mentioned products will be respected in full.

For any further questions please send an email to <mailto:diva.server@eicon.com>