

End Of Life Announcement Diva Server BRI ISA

Eicon Networks has decided to withdraw the following products from the marketplace as of **July 1st 2001**:

- Diva Server BRI ISA NA/Int'
- Diva Server BRI ISA Aust
- Diva Server BRI ISA Germany
- Diva Server BRI ISA Japan
- Diva Server BRI ISA NT1
- Diva Server BRI ISA UK

Migration Path

The table below shows the replacements and the respective ordering numbers for discontinued products.

EOL product	Product code	Suggested Replacement	Product code
Diva Server BRI-2M PCI	305-212	Diva Server BRI-2M 2.0	306-162
Diva Server BRI-2M PCI Australia	305-218	Diva Server BRI-2M 2.0 Australia	306-192
Diva Server BRI-2M PCI Japan	305-260	Diva Server BRI-2M 2.0	306-162
Diva Server BRI-2M PCI Germanic	305-253	Diva Server BRI-2M 2.0	306-162
Diva Server BRI-2M PCI + NT1	305-290	Diva Server BRI-2M 2.0 + NT1	306-165
Diva Server BRI-2M PCI UK	305-945	Diva Server BRI-2M 2.0 UK	306-164

Support and Inventory Policy

These products are no longer manufactured and sold by Eicon. EOL products will not receive software feature updates or support for new operating systems.

Telephone and email installation advice for EOL products is provided where drivers are available for currently supported operating systems.

All contractual warranties for the above mentioned products will be respected in full.

For any further questions please send an email to <mailto:diva.server@eicon.com>