

End Of Life Announcement

Diva Server PRI 1.0

Eicon Networks has decided to withdraw the following products from the marketplace:

- Diva Server PRI-0M PCI
- Diva Server PRI-0M Australia
- Diva Server PRI-0M Japan
- Diva Server PRI-9M
- Diva Server PRI-23M
- Diva Server PRI-30M

Migration Path

The table below shows the replacements and the respective ordering numbers for discontinued products.

| EOL product | Product code | Suggested Replacement | Product code |
|------------------------------|---------------------|------------------------------|---------------------|
| Diva Server PRI-0M PCI | 305-208 | Diva Server PRI-0M 2.0 | 305-478 |
| Diva Server PRI-0M Australia | 306-178 | - | - |
| Diva Server PRI-0M Japan | 305-262 | Diva Server PRI-0M 2.0 | 305-478 |
| Diva Server PRI-9M | 305-209 | Diva Server PRI-8M 2.0 | 305-471 |
| Diva Server PRI-23M | 305-210 | Diva Server T1/PRI-24M 2.0 | 305-981 |
| Diva Server PRI-30M | 305-211 | Diva Server PRI-30M 2.0 | 305-982 |

Support and Inventory Policy

These products are no longer manufactured and sold by Eicon. EOL products will not receive software feature updates or support for new operating systems.

Telephone and email installation advice for EOL products is provided where drivers are available for currently supported operating systems.

All contractual warranties for the above mentioned products will be respected in full.

For any further questions please send an email to diva.server@eicon.com